Work Order (Bid Form)

AUDITOR: Anndra Jackson

(901) 864-2903 anndraj@gmail.com

WORK ORDER INFORMATION

Work Order Name: WO/90009MD2629
Work Order Type: Weatherization
Audit Name: 90009MD2629

CLIENT INFORMATION

Client Name: Address:

Client ID: 90009MD2629

Alt. Client ID:

AGENCY INFORMATION

Agency: Metropolitan Development and Housing Agency Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built 1957 SQ FT 1603 Wood Exterior/Drywall Interior Auditor ANNDRA JACKSON Conducted 3/24/2012

Alt. Client ID:

Measur	e 1 Infilt	ration Redctn			Componen	ts			Inspected
Commen	2) WD2- 3) WD4- 4) WD5, 5) WD5 not spec 6) WD7- 7) WD1- 8) WD1- 10) WD1- 10) WD1- 11) WD1- 12) DR1 13) DR3 14) Seal 15) Seal 16) Seal	3-24X64-C/S Ext and In- 524X64-C/S Ext and In- 524X64-C/S Ext frame. WD6-36X55-C/S Ext has significant air leakage ifically determine source 44X44-C/S Ext and Int. 1-36X55-C/S int. 2-36X55-Reglaze and c/s 13-36X46-C/S Ext 15-44x55-c/s ex and int36X80-FRNT DRInstall 1-32X80-BCK DR-Install 1-32X80-BCK DR-Install 1-32X80-BCK DR-Install 1-312X80-BCK DR-Install 1-32X80-BCK DR-Install	t frame S ge at top e of air lea s ext. C/S s ext. Il d/s and d/s and w/ nen from a under kitcl t nd faucet	seems kage. int. w/s. C /s. addition nen, hall	s to be open Needs to be S int frame all bath and bath dining room	sealed.		ΚS	
					Estimated	·		Actual	
# Material	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscell	aneous Su	Infiltration Reduction	Each	1					
Other Det	ail								
		_		Measur	e Sub Total:			Sub Total:	
Field No	tes:								_

•	<i>Measur</i> e 2 Refr	igerator Rplcmnt			Componen	ts		1	Inspected
C	omment Energy 18.2 cu								
	Contrac	tor must remove old refri	igerator ar	ıd disp	ose of prope Estimated	-		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0	Refrigerators	ANY - ANY	Each	1					
	-							L L	
	Other Detail								
<u> </u>				Measur	e Sub Total:		<u>-</u>	Sub Total:	
Γ	Field Notes:								
	Measure 3 DWI	l Tank Insulation			Componen	ts		ı	Inspected
	omment 40 GAL Low Bo	Electric DWH	moved brfo		k can be wr	apped.			Inspected
C	omment 40 GAL Low Boy Washer	Electric DWH y. /Dryer will need to be rer		ore tan	k can be wr Estimated	apped.		Actual	
C	omment 40 GAL Low Boy Washer Material / Labor	Electric DWH y. /Dryer will need to be rer Description / Comment	Units	Ore tan	k can be wr	apped.	Qty		Inspected
C	omment 40 GAL Low Boy Washer	Electric DWH y. /Dryer will need to be rer		ore tan	k can be wr Estimated	apped.	Qty	Actual	
# 1	omment 40 GAL Low Boy Washer Material / Labor	Electric DWH y. /Dryer will need to be rer Description / Comment	Units	Ore tan	k can be wr Estimated	apped.	Qty	Actual	
# 1	omment 40 GAL Low Boy Washer Material / Labor Hot Water Equip Labor	Electric DWH y. /Dryer will need to be rer Description / Comment DHW Tank Insulation	<i>Units</i> Each	Ore tan	k can be wr Estimated	apped.	Qty	Actual	
# 1	omment 40 GAL Low Boy Washer Material / Labor Hot Water Equip	Electric DWH y. /Dryer will need to be rer Description / Comment DHW Tank Insulation	<i>Units</i> Each	Ore tan	k can be wr Estimated	apped.	Qty	Actual	
# 1	omment 40 GAL Low Boy Washer Material / Labor Hot Water Equip Labor	Electric DWH y. /Dryer will need to be rer Description / Comment DHW Tank Insulation	<i>Units</i> Each	Ore tan	k can be wr Estimated	apped.	Qty	Actual	
# 1 2	omment 40 GAL Low Boy Washer Material / Labor Hot Water Equip Labor	Electric DWH y. /Dryer will need to be rer Description / Comment DHW Tank Insulation	Units Each Each	Qty 1 1	k can be wr Estimated	apped.		Actual	

C	<i>Measur</i> e 4 DWF	l Pipe Insulation			Componer	nts		I	nspected
_	comment Wrap ar	nd first 5ft of pipe wrap.							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail								
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 5 Attic	Ins. R-11			Componer	nts A1			Inspected
_	Comment 2x8x16	e			oompono.	, , ,			
		ipprox 625							
	Insulate	attic with 8" of blown ce							
	Install W	//S and D/S around 32x	80 (horizo	ntal dr					
ш		5			Estimated	d			
	Material / Labor			•		T		Actual	
1	Insulation	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
1		Attic Insulation -	<i>Units</i> SqFt	Qty 625	Unit Cost	Total	Qty		Total
		Attic Insulation - Cellulose, Blown - R-11	SqFt	625	Unit Cost	Total	Qty		Total
	Labor	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation -			Unit Cost	Total	Qty		Total
	Labor	Attic Insulation - Cellulose, Blown - R-11	SqFt	625	Unit Cost	Total	Qty		Total
		Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt	625	Unit Cost	Total	Qty		Total
2	Miscellaneous Su	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt	625	Unit Cost	Total	Qty		Total
2		Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt	625	Unit Cost	Total	Qty		Total
2	Miscellaneous Su	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt	625	Unit Cost	Total	Qty		Total
2	Miscellaneous Su	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt Each	625 625 1		Total		Unit Cost	Total
2	Miscellaneous Su Other Detail	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt Each	625 625 1	Unit Cost	Total			Total
2	Miscellaneous Su	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt Each	625 625 1		Total		Unit Cost	Total
2	Miscellaneous Su Other Detail	Attic Insulation - Cellulose, Blown - R-11 Attic Insulation - Cellulose, Blown - R-11	SqFt SqFt Each	625 625 1		Total		Unit Cost	Total

Measure 6 Inst	all Bathroom Exhaust F	an		Componen	ts			Inspected
	exhaust fan, vent to exter g light/switch. No existing		•	athroom.		om		
				Estimated	<u> </u>		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	y Bathroom exhaust fan	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Magazir	Sub Total] []	Sub Total:	
		ı	weasur	e Sub Total:]	Sub Total.	
	sement/C.rawisbace)							
Comment SQ FT Install p	sement/Crawlspace) 1603 per TFG guidelines. Using ers. Secure and overlap 1			end 12" up	foundatio	on walls	3	
Comment SQ FT Install p	1603 per TFG guidelines. Using			end 12" up <i>Estimate</i> d		on walls	S Actual	
Comment SQ FT Install p	1603 per TFG guidelines. Using			·		on walls		Total
Comment SQ FT Install p and pie	1603 Der TFG guidelines. Using rs. Secure and overlap 1 Description / Comment	2" at sean	ns.	Estimated	<u> </u>		Actual	Total
Comment SQ FT Install pand pie # Material / Labor	1603 Der TFG guidelines. Using ers. Secure and overlap 1. Description / Comment Basement / crawlspace	2" at sean <i>Unit</i> s	Qty	Estimated	<u> </u>		Actual	Total
Comment SQ FT Install p and pie # Material / Labor Health and Safety	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt	Qty 1603	Estimated	<u> </u>		Actual	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt	Qty 1603	Estimated	<u> </u>		Actual	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt	Qty 1603	Estimated	<u> </u>		Actual	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt SqFt	Qty 1603 1603	Estimated	<u> </u>	Qty	Actual	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt SqFt	Qty 1603 1603	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor Other Detail	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt SqFt	Qty 1603 1603	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor Other Detail	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt SqFt	Qty 1603 1603	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor Other Detail	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam <i>Units</i> SqFt SqFt	Qty 1603 1603	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	Total
Comment SQ FT Install pand pie # Material / Labor Health and Safety Labor Other Detail	1603 Der TFG guidelines. Using ers. Secure and overlap 1 Description / Comment Basement / crawlspace vapor barrier	2" at seam Units SqFt SqFt	Qty 1603 1603	Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	Total